



**Log of Saab AB DOA 21J.108  
EASA STC by type  
2022-12-22**

Ref  
Binder 11  
Sheet  
1 (2)

## SUPPLEMENTAL TYPE CERTIFICATE LOG

STC Number	Reference	Issue	Description	Applicable Aircraft	Approval date
<b>Beech (Textron Aviation) (Former Hawker Beechcraft, Beechcraft Aircraft Corporation)</b>					
EASA.A.S.02550	TDM06-04	A	Introduction of BRNAV and TAWS Class B.	Beech A100	2006-04-19
EASA STC 10063774	TDM17-24	A	Installation of SATCOM using Iridium satellites model: Flightcell DZMx.	TEXTRON AVIATION INC. Type: A100, 200, 300, 1900	2017-11-20
EASA STC 10069824	TDM19-05	A	Installation of SATCOM system Flightcell DZMx with Cabin Intercom/ Attendant Call	TEXTRON AVIATION INC. Type: A100, 200, 300, 1900 Model: B200GT	2019-05-10
FAA STC SA04461NY	TDM19-05	A	Installation of SATCOM system Flightcell DZMx with Cabin Intercom/ Attendant Call	TEXTRON AVIATION INC. Type: A100, 200, 300, 1900 Model: B200GT	2020-02-25
<b>Casa 212</b>					
EASA A.S.00480	TDM 04-14	3	ACAS II (Collins TCAS 4000) and dual Mode S Transponders. (Collins TDR-94).	CASA C-212	2005-01-10
EASA A.S.00694	TDM 04-18	C	ACAS II (Honeywell TCAS 2000) and single Mode S Transponder. (L-3 ACSS).	CASA C-212	2005-04-11
EASA 10038972	TDM10-05	G	New Cabin Layout for Maritime Surveillance System in Casa C-212	CASA C-212	2012-04-27
<b>Cessna</b>					
EASA.A.S.03192	TDM07-18	A	Replacement of Mode S Transponders in Cessna 560 to comply with Enhanced Surveillance.	Cessna 560	2007-12-04
EASA.A.S.03193	TDM07-19	A	Replacement of Mode S Transponders in Cessna 650 to comply with Enhanced Surveillance.	Cessna 650	2007-12-04
<b>Eurocopter</b>					
EASA 10033697	TDM08-30	B	Installation of provisions for the New TopEye Mission Box to be mounted on the structure of the Under Carriage of AS355 as a variant to TopEye Laser Altimetry Pod.	Eurocopter AS355	2011-02-08
<b>Learjet</b>					
EASA A.S.00255	TDM 03-17	5	ACAS II 7.0 and 7.1. (Collins TCAS 4000) and dual Mode S Transponders (Collins TDR-94)	Learjet 35A	2004-10-28
EASA AFMS 10054782		A			2015-09-15
<i>Annex A ACAS Support Unit</i>			<i>EUROCONTROL ACAS II Compliant Notification</i>	Learjet 35A	2005-09-05
EASA.A.S.01583	TDM 03-03	A	Target Mission Operator's Console	Learjet 35A	2005-11-17
EASA.A.S.02582	TDM06-01	A	Mission Power and Electrical Cable Feed Thru in Baggage Floor.	Learjet 35A	2006-06-20
EASA.A.S.03465	TDM08-06	A	Installation of Honeywell MK VIII EGPWS in Learjet 35A with Mission Inhibit System.	Learjet 35A	2008-09-10
EASA.A.S.03532	TDM08-02	A	Mode S Enhanced Surveillance Upgrade.	Learjet 35A	2008-08-01
EASA 10053365	TDM14-48	A	ACAS II Honeywell CAS 67B Change 7.1	Learjet 35A	2015-05-20
EASA STC 10073509	TDM20-02	C	Installation of ADS-B out capability In Learjet 35A.	Learjet 35A	2020-06-16



**Log of Saab AB DOA 21J.108  
EASA STC by type  
2022-12-22**

Ref  
Binder 11  
Sheet  
2 (2)

## SUPPLEMENTAL TYPE CERTIFICATE LOG

STC Number	Reference	Issue	Description	Applicable Aircraft	Approval date
<b>LEONARDO S.p.A.</b>					
EASA STC 10078618	TDM21-04	A	Inflation System for A109 Emergency Flotation System – Certification of a new inflation system as an alternative to the existing Moog's inflation system.	LEONARDO S.p.A. A109/A119	2022-02-15
FAA STC SR00084IB	TDM21-04	D	Installation of Alternative Inflation System for Emergency Flotation System must be in accordance with Saab AB Master Data List Doc. No. TDM21-04-MDL, Issue D, dated November 7, 2022, or later EASA approved revisions.	LEONARDO S.p.A. A109	2022-12-19
<b>Lockheed</b>					
P-EASA.A.S.03618 SAP 0060004512 STC10031209 R1 STC10031209 R2	TDM07-37	A	Installation of Saab Missile Protection System  (Rev. 1: Limitations for Continued Airworthiness in accordance with Technical Visa).  (Rev. 2: Limitations for Continued Airworthiness in accordance with TDM07-37-4-ICA).	Lockheed Martin L-382	EASA STC Rev 2: 2010-12-20
GACA/VAL-037 GACA/VAL-037 Rev. 1					GACA Rev 1 2011-01-30
<b>MD Helicopters</b>					
EASA 10057706	TDM14-30	A	Increase payload of Data Acquisition Module – Hardware, DAM-H, Vision Mount Module Installation.	MDH inc. MECAER AG SPA Type: D369, 500N, 600N, NH-AMD500 Model: 369D, 369E, 369H, 369HE, 369HM, 369HS, NH-500D	2016-04-06
<b>Mitsubishi</b>					
EASA.A.S.03472	TDM08-03	A	Garmin GTX330/330D upgrades for compliance with Enhanced Surveillance (EHS) requirements.	Mitsubishi MU-2B-20/-26	2008-03-27
EASA 10029935	TDM10-03	A	Installation Provisions/Video Signal in Mitsubishi MU-2B rear pressure bulkhead.	Mitsubishi MU-2B-20/-26	2010-05-04
EASA 10040413	TDM11-15	A	Installation of aft Pressure Bulkhead and Pressure feed Thru provisions for Antenna / Electrical Connectors	Mitsubishi MU-2B-20/-26	2012-07-02